




Source document updated			TESTER NAME	SIGNATURE	DATE	Activity	Comp	Date	Drg.No.			Signalling Control U.K.	
Version	Prod	Check	1			Prep. Inspection			Produced	JC	MAR' 95	D. A. M. ARCHITECTURE	
			2			Prep. W.C. and Cont			Checked	DW			
			3			Prep. S. & F/C.F.T.			Scale				
			4			Cable core Loc End			Issued				
			5			Cable core Equ End							
Complete tester details in your own marking colour. Sign off for completed activities.						Changeover Comp							Glasgow Projects Group
												Sht. No.	7-1
												Version	




Source document updated			TESTER NAME		SIGNATURE		DATE		Activity		Comp		Date		Drg.No.				● Signalling Control U.K.			
Version	Prod	Check	1						Prep. Inspection				Produced	JC		MAR' 95	CONTROL CARD BLOCK SCHEMATIC				Glasgow Projects Group	
			2						Prep. W.C. and Cont				Checked	DW							Sht. No. 7-2	
			3						Prep. S. & F/C.F.T.												Version	
			4						Cable core Loc End				Scale									
			5						Cable core Equ End				Issued									
Complete tester details in your own marking colour. Sign off for completed activities.									Changeover Comp													




Source document updated			TESTER NAME		SIGNATURE		DATE		Activity		Comp	Date	Drg.No.		● Signalling Control U.K.		MULTIPLEXING CARD BLOCK SCHEMATIC		Glasgow Projects Group	
Version	Prod	Check	1						Prep. Inspection				Produced	JC		MAR' 95			Sht. No.	7-3
			2						Prep. W.C. and Cont				Checked	DW					Version	
			3						Prep. S. & F.C.F.T.				Scale							
			4						Cable core Loc End				Issued							
			5						Cable core Equ End											
			Complete tester details in your own marking colour. Sign off for completed activities.						Changeover Comp											







Source document updated			TESTER NAME		SIGNATURE	DATE	Activity		Comp	Date	Drg.No.			● Signalling Control U.K.	
Version	Prod	Check	1				Prep. Inspection				Produced	JC		MAR' 95	
			2				Prep. W.C. and Cont				Checked	DW			
			3				Prep. S. & F/C.F.T.								
			4				Cable core Loc End				Scale				
			5				Cable core Equ End								
			Complete tester details in your own marking colour. Sign off for completed activities.				Changeover Comp				Issued				
SIMPLE ROK/TOFF WIRING BLOCK SCHEMATIC															
Glasgow Projects Group															
Sht. No. 7-5															
Version															




Source document updated			TESTER NAME		SIGNATURE		DATE		Activity		Comp		Date		Drg.No.		● Signalling Control U.K.					
Version	Prod	Check	1						Prep. Inspection				Produced	JC		MAR' 95	PRACTICAL ROK/TOFF WIRING BLOCK SCHEMATIC		Glasgow Projects Group			
			2						Prep. W.C. and Cont				Checked	DW							Sht. No. 7-6	
			3						Prep. S. & F/C.F.T.										Version			
			4						Cable core Loc End				Scale									
			5						Cable core Equ End				Issued									
Complete tester details in your own marking colour. Sign off for completed activities.									Changeover Comp													




Source document updated			TESTER NAME	SIGNATURE	DATE	Activity	Comp	Date	Drg.No.	Signalling Control U.K.			CONTROL CARD LINK SETTINGS		Glasgow Projects Group	
Version	Prod	Check	1			Prep. Inspection			Produced	JC		MAR' 95	Sht. No. 7-7		Version	
			2			Prep. W.C. and Cont			Checked	DW						
			3			Prep. S. & F/C.F.T.			Scale							
			4			Cable core Loc End			Issued							
			5			Cable core Equ End										
						Changeover Comp										
						Complete tester details in your own marking colour. Sign off for completed activities.										



Source document updated			TESTER NAME	SIGNATURE	DATE	Activity	Comp	Date	Drg.No.			<div> <div></div> <div>Signalling Control U.K.</div> </div> <div>MULTIPLEXING CARD OVERLAY LINK SETTINGS</div>	Glasgow Projects Group	
Version	Prod	Check	1			Prep. Inspection			Produced	JC	MAR' 95		Sht. No.	7-8
			2			Prep. W.C. and Cont			Checked	DW			Version	
			3			Prep. S. & F/C.F.T.			Scale					
			4			Cable core Loc End			Issued					
			5			Cable core Equ End								
Complete tester details in your own marking colour. Sign off for completed activities.						Changeover Comp								



Source document updated			TESTER NAME	SIGNATURE	DATE	Activity	Comp	Date	Drg.No.			Signalling Control U.K.	
Version	Prod	Check	1			Prep. Inspection			Produced	JC	MAR' 95	DEMULPLEXING CARD OVERLAY LINK SETTINGS	
			2			Prep. W.C. and Cont			Checked	DW			
			3			Prep. S. & F./C.F.T.			Scale				
			4			Cable core Loc End			Issued				
			5			Cable core Equ End							
Complete tester details in your own marking colour. Sign off for completed activities.						Changeover Comp						Glasgow Projects Group	
												Sht. No.	7-9
												Version	



Source document updated			TESTER NAME	SIGNATURE	DATE	Activity	Comp	Date	Drg.No.			● Signalling Control U.K.			
Version	Prod	Check	1			Prep. Inspection			Produced	RCS		MAR' 95	MODEM CARD LINK SETTINGS		Glasgow Projects Group
			2			Prep. W.C. and Cont			Checked	DW					Sht. No. 7-10
			3			Prep. S. & F.C.F.T.			Scale						Version
			4			Cable core Loc End			Issued						
			5			Cable core Equ End									
			Complete tester details in your own marking colour. Sign off for completed activities.			Changeover Comp									